

SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 631 52 01

Horizontal Datum: NAD 83/91

Vertical Datum: NAVD 88

Control Point ID: Book: 631 Page: 52 Pt#: 01

Established By: WJA

Date: 10/26/95

Revised 1/24/01

Section: 7

Township: 28 N

Range: 5 E

LATTITUDE: (5 decimal places) 47 55 40.78392

LONGITUDE: (5 decimal places) 122 12 40.82791

ORTHOMETRIC HEIGHT: 434.90 Feet

132.558 Meters

Washington State Plane Coordinates – North Zone

Edited by Geodetic Consultants in 1996, revised 5/5/97 and 02/15/01.

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	341528.708	1302600.924	0.999947724	-01 01 33.4
Meters	104098.1584	397033.5557		

HORIZONTAL DATA:

Horizontal position established by: WJA

____ resection survey, comments

x GPS survey, GPS adjustment software used: Leica rapid static GPS and Leica SKI adjustment software

____ other, explain: _____

surveyor's estimated relative positional accuracy: ____ .01 ft. @ ____ 95% confidence

surveyor's estimated absolute positional accuracy: ____ .05ft. @ ____ 95% confidence

VERTICAL DATA:

Vertical position established by: Pertect

x differential leveling to: 3 order accuracy

____ GPS survey, accuracy within ____ ft ____ meters

surveyor's estimated relative positional accuracy: ____ ft @ ____ % confidence

surveyor's estimated absolute positional accuracy: ____ .03ft @ ____ 95% confidence

MONUMENT DESCRIPTION

A 4-inch diameter iron pipe with a lead plug and brass tack in an iron monument box.

TO REACH

Located on Beverly Boulevard, south of Seinic Drive, southeast of the a sanitary sewer manhole cover.

REFERENCES

Az from North	Distance	Reference Description
---------------	----------	-----------------------

Month & Year Recovered:
09/2000

Condition of Mark:
GOOD

Recovered By:
Pertect Engineering Inc.